Tuesday, 6/27/2006 11:45:09 AM Linda Lacelle **Process Sheet Drawing Name** : D26672 : CC-DAR01 Dart Aerospace Ltd. Customer : 27704 Job Number : 10804 **Estimate Number** : D26672 **Part Number** P.O. Number - RTN495 : 6/27/2006 S.O. No. : **Drawing Number** This Issue : NC **Project Number** Prsht Rev. First Issue : // Type **Drawing Revision** : 27703 Material **Previous Run** : 7/4/2006 Qty: 1 Um: Each **Due Date** Written By Checked & Approved By Comment **Additional Product** Job Number: Description: **Machine Or Operation:** Seq. #: INSPECT WORK TO CURRENT STEP 1.0 QC5 Comment: INSPECT RTN 495 2.0 D26672 Saddle, RH, Aft, Out Comment: Qty.: 1.0000 Each(s)/Unit Total: 1.0000 Each(s) Saddle, LH, Aft, Out ORIGINAL B/N 9056 POWDER COATING 3.0 POWDER COATING Comment: POWDER COATING TOUCH UP SADDLES AS NECESSARY **PER RS1004** INSPECT POWDER COAT/CHEMICAL CONVERSION 4.0 QC3 Comment: INSPECT POWDER COAT/CHEMICAL CONVERSION PACKAGING RESOURCE #1 5.0 PACKAGING 1 Comment: PACKAGING RESOURCE #1 NIA Clase @ ID & STOCK WITH NEW B/N

Date: User:

Tuesday, 6/27/2006 11:45:09 AM

Linda Lacelle

Process Sheet

Customer: CC-DAR01 Dart Aerospace Ltd.

Drawing Name: D26672

Job Number: 27704

Part Number: D26672

Job Number:



Seq. #:

Machine Or Operation:

Description:

6.0

DOCUMENT CONTROL





Comment: DOCUMENT CONTROL

Job Completion



C207/03/22

